



Appendix E Personal Injury Collision Data



EDR065 Thornbury various (siteA) Accident Date BETWEEN '01-Jan-2013' AND '31-Dec-2017'

<u>131302710</u>	SLIGHT	365415/189113	01/04	/2013 18:	30					
LOCATION	A38 Gloucester Road at Junction with Grovesend, Thornbury									
DESCRIPTION					V1 FAILED ON THE HICH WAS STATIONA					
VEH	IICLES	DRIVER		CASUALTIES		VEH	SEX	AGE		
1	Other: Motor ve	hicle Male	26	1 Driver/R	ider SLIGHT	2	Male	57		
2	Car	Male	57							
151503330		365055/189485	22/04		22					
LOCATION	Grovesend Roa	d at Junction with Mo	orton W	ay, Thornbury						
DESCRIPTION	V1 TRAVELL	ING TOWARDS TY	THERI	NGTON ON G	ORVESEND ROAD EN	TERED TH	HE RAB TO)		
			(CYC)) ENTERED TI	HE ROUNDABOUT FR	OM MORT	EN WAY			
	AND COLLID	ED WITH V1.								
VEH	IICLES	DRIVER		CASUALTIES		VEH	SEX	AGE		
1	Car	Male	23	1 Driver/R	ider SERIOUS	S 2	Male	51		
2	Pedal Cycle	Male	51							
<u>161606650</u>	SERIOUS	365044/189459	13/08	/2016 15:	20					
LOCATION	Midland Way a	t Junction with Grove	esend R	oad, Thornbury						
DESCRIPTION					DLAND WAY. AS V1			,		
					D ROAD INTO THE PA					
			ION, B		WAND CAME TO A					
VEH	IICLES	DRIVER		CASUALTIES		VEH	SEX	AGE		
1	Car	Female	41	1 Driver/R	ider SERIOUS	S 1	Female	41		
<u>171800013</u>	SLIGHT	365475/189123	08/10	/2017 16:	00					
LOCATION	Tytherington R	oad at junction with A	A38 Glo	oucester Road,	Thornbury					
DESCRIPTION	V2 HAS STOP	PED IN A QUEUE A	T A RI	ED LIGHT ON	TYTHERINGTON ROA	AD AT ITS	JUNCTION	N		
					N THE REAR BY V1. I					
	HER FOOT SI	LIPPED OFF THE CL	UTCH	AND SHE DR	OVE STRAIGHT INTO	THE REA	R OF V2.			
VEH	IICLES	DRIVER		CASUALTIES		VEH	SEX	AGE		
1	Car	Female	43	1 Driver/R	ider SLIGHT	1	Female	43		
2	Car	Male	79							

Narrative Report 24-April-2018 1



EDR065 Thornbury various (siteB) Accident Date BETWEEN '01-Jan-2013' AND '31-Dec-2017'

151500853 SLIGHT 366522/190513 04/01/2015 14:10

LOCATION A38 Gloucester Road, at Junction with B4061 Old Gloucester Road, Buckover

DESCRIPTION V2 (M/C) WAS TRAVELLING S/B ON A38 TOWARDS ALVESTON WHEN V1 T/RIGHT FROM THE

B4061 OLD GLOUCESTER ROAD INTO THE PATH OF V2 AND COLLISION OCCURRED.

 VEHICLES
 DRIVER
 CASUALTIES
 VEH
 SEX
 AGE

 1
 Car
 Female
 43
 1
 Driver/Rider
 SLIGHT
 2
 Male
 28

 2
 M/cycle > 500cc
 Male
 28

151505771 SLIGHT 366516/190510 24/07/2015 16:51

LOCATION A38 (By White Horse Inn) Jnc with B4061, Buckover

DESCRIPTION V1 TRAV S/B ON A38 IN LANE 2, APPROACHING OFFSIDE JNC WITH B4061. V2 TRAV N/B IN

LANE 1 IN SLOW MOVING TRAFFIC. V1 INDICATING TO T/RT INTO B4061 AND PULLS ACROSS

INTO PATH OF V2.

VEHICLES DRIVER CASUALTIES VEH SEX AGE 1 Car Male 55 Driver/Rider SLIGHT 1 55 1 Male 18 2 Driver/Rider **SLIGHT** 2 2 Car Male 18 Male

<u>161607311</u> SLIGHT 367153/191298 22/09/2016 12:50

LOCATION A38, Whitfield


DESCRIPTION V1 WAS COMING OUT OF THE 60MPH SPEED LIMIT INTO THE 40MPH SPEED LIMIT AND

STARTED TO SLOW DOWN. WHILST DOING SO, D1 GOT THEIR FOOT STUCK AMONGST THE

PEDALS CAUSING V1 TO SLOW AND THEN STALL. V2 DROVE INTO THE REAR OF V1.

VEHICLESDRIVERCASUALTIESVEH SEXAGE1 CarMale23 1 PassengerSLIGHT2 Female682 CarMale69

Narrative Report 24-April-2018 1



EDR065 Thornbury various (siteC) Accident Date BETWEEN '01-Jan-2013' AND '31-Dec-2017'

 131301762
 SLIGHT
 363672/190106
 09/02/2013
 14:17

 LOCATION
 B4061 High Street Junction with Castle Court, Thornbury

DESCRIPTION C1 (PED) WAS CROSSING THE HIGH STREET WHEN V1 T/RT OUT OF CASTLE COURT ONTO

THE HIGH STREET AND COLLIDED WITH C1.

VEHICLES DRIVER **CASUALTIES** VEH SEX AGE 1 Car Male 38 **SLIGHT** 64 Pedestrian 1 Male 363619/190303 SLIGHT 13/01/2014 13:39 141401019 LOCATION Castle Street, Thornbury DESCRIPTION V1 WAS TRAV S/B ON CASTLE STREET TOWING AN AGRICULTURAL TRAILER WHEN C1 (PED) STEPPED OUT FROM BETWEEN 2 PARKED VEHICLES TO CROSS THE ROAD INTO THE PATH OF V1. V1 WAS TRAV AT A SLOW SPEED AND D1 TRIED TO AVOID C1, BUT COLLISION

OCCURRED.

VEHICLES

DRIVER

CASUALTIES

VEH SEX

AGE

1 Agric Veh

Male

58 1 Pedestrian

SLIGHT

1 Female

90

141408958 SLIGHT 363778/190085 06/12/2014 19:12

LOCATION Quaker Lane, Thornbury

DESCRIPTION V1 TRAVELLED FROM HIGH STREET INTO QUACKERS LANE. AS D1 NEGOTIATED A LEFT

HAND BAND, C1 (PED) CROSSED N/B INTO THE PATH OF V1 AND WAS KNOCKED OVER AS V1 $\,$

PASSED.

VEHICLESDRIVERCASUALTIESVEH SEXAGE1 CarMale251 PedestrianSLIGHT1 Female82

<u>161601831</u> SLIGHT 363815/190311 19/02/2016 08:32

LOCATION B4061 Gloucester Road, at its Junction with The Elms Centre, Thornbury

DESCRIPTION VEHS TRAVELLING NE/B AWAY FROM THORNBURY HIGH STREET WHEN TRAFFIC BECAME

STATIONARY BEHINF V2 WHICH WAS STATIONARY WITING TO T/RIGHT INTO THE ELMS MEDICAL CENTRE. V1 (M/C) O/TOOK LINE OF STATIONARY VEHS. BUT V2 T/RIGHT AS V1


WAS PASSING AND R1 COLLIDED WITH THE O/S OF V2.

 VEHICLES
 DRIVER
 CASUALTIES
 VEH SEX
 AGE

 1 M/cycle <= 50cc</td>
 Male
 16 1 Driver/Rider
 SLIGHT
 1 Male
 16

 2 Car
 Female
 42
 42

Narrative Report 24-April-2018 1



EDR065 Thornbury various (siteD) Accident Date BETWEEN '01-Jan-2013' AND '31-Dec-2017'

 141404256
 SLIGHT
 364466/191271
 16/06/2014
 16:20

 LOCATION
 B4061 Gloucster Road, at its Junction with Butt Lane, Thornbury


DESCRIPTION V1 (CYC) TRAVELLING N/B ALONG GLOUCESTER ROAD TWRDS ROCKHAMPTON. AS R1

PASSED THE JUNCTION OF BUTT LANE, V2 T/LFT ONTO GLOUCESTER ROAD, CAUSING R1 $\,$

TO SWERVE, LOSE CONTROL AND FALL FROM THEIR BIKE.

VEHICLESDRIVERCASUALTIESVEH SEXAGE1 Pedal CycleMale31 1 Driver/RiderSLIGHT1 Male312 CarMale57

Narrative Report 24-April-2018



EDR072 M5 J14 Accident Date BETWEEN '30-Apr-2013' AND '01-May-2018'

141401552 LOCATION DESCRIPTION	SLIGHT 368780/ M5 Junction J14 VEHS TRAV N/B ON SLOWED AND STOP	THE M5 WH		THEY PASSI	ED J14 THERE WAS I								
VEH	IICLES	DRIVER		CASUALTIES		VEH	SEX	AGE					
	Car	Female	Unk		er SLIGH		Female	Unk					
2	Car	Male	30	2 Passenge	er SLIGH	Т 2	Male	1					
151504561 SLIGHT 368773/193235 24/06/2015 08:19 DESCRIPTION B4509 Junction with M5 Junction 14, Failfield DESCRIPTION V1 (M/C)TRAVELLING E/B ON B4509 FROM THE A38 BEHIND A TRACTOR WHEN THE TRACTOR STOPPED TO ALLOW O/C V2 TO T/RIGHT ONTO THE M5 SLIP ROAD. R1 U/TOOK THE TRACTOR AND COLLIDED WITH V2. VEHICLES DRIVER CASUALTIES VEH SEX AGE													
		DRIVER		CASUALTIES				AGE					
	M/cycle 125 - 500cc	Male		 Driver/R Passenge 			Male Female	30 9					
2	Car	Female	33	2 Passenge	sı SLIGH	1 2	Female	9					
1	SLIGHT 369111/ M5 J14-15 (Exact locat IT WAS APPEAR THA TRAFFIC. WHEN V1 1 OFFER D2 £20 FOR D IICLES Van/Goods < 3.5t Car	ion unknown) AT THE VEH HIT THE R/C	IS WERI D V2. A JT THEN	E TRAV S/B (CONVERSA N DROVE OF CASUALTIES	ON THE M5 BETWEE TION TOOK PLACE F WITHOUT LEAVIN	WHERE D1 NG CORREC VEH	TRIED TO	AGE 32					
SLIGHT 369178/193090 07/06/2015 12:02													
2	Car	Male	32										
151506869 SLIGHT 368607/192944 28/08/2015 22:08 LOCATION M5 J15-14 DESCRIPTION V1 AND V2 TRAVELLING N/B ON THE M5. V1 WAS IN L2 AND V2 IN L3 OVERTAKING VEHICLES WHEN V1 MOVED INTO L3 AND COLLIDED WITH V2 AND LOST CONTROL.													
VEL	IICLES	DRIVER	(CASUALTIES		VEH	SEX	AGE					
1	Car	Male		1 Driver/R	ider SLIGH	Γ 1	Male	46					
1		Male Male	46 25	1 Driver/R	ider SLIGH	Γ 1	Male	46					
1 2 1 51507990 LOCATION DESCRIPTION VEH	Car Car SLIGHT 368921/ M5 J14 (M/P 118/7) V1 WAS TRAVELLIN SWERVED FROM LA UP A BANK AND FLI	Male 193342 IG S/B IN LA NE 3 TO LA PPED ONTO DRIVER	25 19/06/2 NE 3 AT NE 1 WI D ITS RO	2015 19 I EXCESS SI HERE IT HIT DOF. V1 WEN CASUALTIES	45 PEED, WHEN D1 LOS V2. V2 LEFT THE C IT ONTO VERGE AN	T CONTROI /W ON THE D STOPPED. VEH	. AND N/S, WENT SEX	AGE					
1 2 1 51507990 LOCATION DESCRIPTION VEH	Car Car SLIGHT 368921/ M5 J14 (M/P 118/7) V1 WAS TRAVELLIN SWERVED FROM LA UP A BANK AND FLI	Male 193342 IG S/B IN LA NE 3 TO LA PPED ONTO	25 19/06/2 NE 3 AT NE 1 WI D ITS RO	2015 19 I EXCESS SI HERE IT HIT DOF. V1 WEN	45 PEED, WHEN D1 LOS V2. V2 LEFT THE C IT ONTO VERGE AN	T CONTROI /W ON THE D STOPPED. VEH	. AND N/S, WENT						

Narrative Report 17-July-2018 1

EDR072 M5 J14 Accident Date BETWEEN '30-Apr-2013' AND '01-May-2018'

161604419 SLIGHT 368580/192852 09/05/2016 14:52

LOCATION M5 J14, Falfield

DESCRIPTION V2 PULLED ONTO HARD SHOULDER WHILE TRAV S/B ON THE M5 & STOPPED DUE TO A

PROBLEM WITH THE WINDSCREEN WIPERS DURING HEAVY RAIN. PASSING V1 COLLIDED

(GLANCING BLOW) WITH OFFSIDE OF V2

VEH SEX VEHICLES DRIVER **CASUALTIES** AGE 1 Goods > 7.5t54 Male 42 1 Driver/Rider **SLIGHT** 2 Male 2 Passenger **SLIGHT** Male 24 2 Goods 3.5 - 7.5t 54 Male

181802472 SLIGHT 368730/193260 28/03/2018 08:12

LOCATION M5 J14 at Junction with B4509

DESCRIPTION V1 WAS LEAVING THE M5 ONTO THE B4509 AT J14. V1 FAILED TO GIVE WAY AT THE

JUNCTION AND PULLED OUT. V2 WHICH WAS TRAVELLING W/B TOWARDS FALFIELD ON

THE B4509 COULD NOT AVOID COLLISION AND HIT THE O/S OF V1.

DRIVER **VEHICLES CASUALTIES** VEH SEX **AGE** 1 Car Male Driver/Rider 38 38 1 SLIGHT Male 2 Passenger **SLIGHT** 2 Female 40 2 Car 46 Male

Narrative Report 17-July-2018 2